

Samples of Photos Taken by ODOT OIS Investigator John Shore on April 22, 2014



View from other side of roadway. Cone is where trucks backed up to guardrail and dumped dirt over the rail. Drive and truck in background are on other side of the creek.

Exhibit 2

Page 2 of 5



Standing at guardrail, cone in other pictures is to immediate right. There is approximately 5-10 feet of gradually sloping terrain, and then at tree on far right slope goes to steep embankment, down to river. There is no accumulation (depth) of material at this point, other than what is under the guardrail. Everything else slid down the embankment.

As shown, creek is clearly visible.



This view is from the drive on the opposite side of the creek. The guardrail where the trucks dumped from is here. Estimate that the embankment is 50-60 feet in height.

Exhibit 2

Page 4 of 5



Standing on the 5-10 feet of gradual slope, just on the other side of the guardrail. Obvious how the material slid down the embankment and into the creek. The dirt here is no deeper than sitting on top of the leaves.

Standing at the guardrail, or perhaps in the cab of a dump truck, the creek would be visible.



Another view of material in creek. Obvious how the material slid down the steep embankment.